



SERVICE BULLETIN

Classification: EM94-007	Reference: NTB94-089	Date: September 13, 1994
-----------------------------	-------------------------	-----------------------------

VG30 ENGINE OIL DIPSTICK CAUTION

APPLIED VEHICLE(S): All VG30i/E or VG30DE equipped models

SERVICE INFORMATION

When performing any service that requires removal of the oil pan, always remove the dipstick before replacing the oil pan. If the dipstick is left in the engine the end of it may become caught between the main bearing beam and the windage tray of the oil pan. The only way to remove the dipstick after it has been caught is to remove the oil pan.

