



+ JPB

# SERVICE BULLETIN

Classification: EL94-014	Section: Electrical	Models: See Below
Reference: TECHNICAL BULLETIN NTB94-101		Date: November 29, 1994

## 1995 MAXIMA AND 240SX CD PLAYER INSTALLATION


**APPLIED MODEL:** 1995 Maxima and 240SX

### SERVICE INFORMATION

Non-CD equipped 1995 Maximas and 1995 240SXs have built in CD connections. The adapter harness supplied with the CD player is not required. The connectors are taped to the radio harness behind the radio.

### SERVICE PROCEDURE

When installing a CD player into a 1995 Maxima or 240SX use the connectors on the vehicle harness. Do not use the adapter harness supplied with the CD player.



Index # **040361**

NISSAN MOTOR CORPORATION U.S.A.  
Technical Communications Department